



STANDARD EXPORT PACKAGING PROCEDURE

For

Zephyr and SLE Products

- 1. Lubricate load chain and other unpainted surfaces, to resist corrosion.**
- 2. Overwrap product with vapor resistance paper.**
- 3. Place in wooden crate (manufactured from processed wood and /or heat treated or fumigated wood meeting ISPM 15), install bracing to add stability to the crating and to prevent shifting of the product inside the container.**
- 4. Add desiccant material to container, prior to covering with wooden lid. No gaps in crating, greater than 1/8” are permitted.**
- 5. Band with plastic strapping, parallel to runners on bottom of crate.**



